

# Oil Field Environmental Incident Summary

**Incident:** 20150827155537      **Date/Time of Notice:** 08/27/2015 15:55

**Responsible Party:** CITATION OIL & GAS CORP.

**Well Operator:** CITATION OIL & GAS CORP.

**Well Name:** CARUS UNIT A 1

**Field Name:** LONE BUTTE

**Well File #:** 8838

**Date Incident:** 3/30/2015      **Time Incident:** 13:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 147

**Rng:** 97

**Sec:** 18

**Qtr:** SE SW

**Location Description:**

**Submitted By:** Lee Ann Elsom

**Received By:**

**Contact Person:** Lee Ann Elsom  
14077 CUTTEN ROAD  
PO BOX 690688  
HOUSTON, TX 77269-0688

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 5 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	63	Gallons			0	gallons
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/23/2016

**Clean Up Concluded:** 5/29/2016

**Risk Evaluation:**

None

**Areal Extent:**

approximately 8' wide x 100' long

**Potential Environmental Impacts:**

Soil was affected by this release, contaminated soil was removed and hauled to a certified landfill.

**Action Taken or Planned:**

Saltwater line was replaced

**Wastes Disposal Location:** contaminated soil was taken to a certified landfill

**Agencies Involved:**

**Updates**

---

**Date:** 9/1/2015    **Status:** Inspection    **Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:** 63.00 gallons

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 7:38 p.m. Sunny, 88 degrees with wind out of the southwest at 10 mph. GPS: N47.54731 W103.08479. The material came off site behind (southwest side) the tank storage area. It headed down the well pad bank and ran about 20 feet toward the west of the site into pasture land. The soil has been removed, straw wattles were installed, and the area was planted with grass. The vegetation is coming up in fair condition. No water was impacted. No additional followup needed for site.

---

**Date:** 11/27/2015    **Status:** Correspondence    **Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spill cleanup report forwarded to the NDDoH.